




Step1 using the plastic adaptors and short tube to locking crossbeam ;locked screwsA

Step2 opening the tripod, and locking the screw B

Step3 using short tube to connection between tube C & D, and locking the screw C

Step4 insert tube C , and locking the screw.